

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

86

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	FC State Com #4	Facility Type	Gas Well
		API #	30-045-27478
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	B-11240-75

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	36	T31N	R9W	1340'	North	800'	East	San Juan

Latitude 36.85803° N Longitude 107.72616° W

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 8 BBL	Volume Recovered – none
Source of Release: Water transfer pump leak	Date and Hour of Occurrence unknown	Date and Hour of Discovery 9/5/08 – 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via email BLM - Kevin Schneider via email	RCVD SEP 24 '08 OIL CONS. DIV.
By Whom? Kristina Kovach	Date and Hour – 9/16/08 – 4:00 p.m.	DIST. 3
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips Company employee discovered a produced water spill of approximately 8 BBL at the FC State Com #4 on 9/5/08. The spill resulted when the water transfer pump malfunctioned. Upon discovery, the pumping unit was isolated and shut down.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids were contained within the berm, but none were recovered. COPC will monitor soil conditions to determine if further remediation is necessary. To prevent reoccurrence, COPC will replace the transfer pump.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kristina L. Kovach</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kristina L. Kovach		Approved by District Supervisor: <i>Bob Bell</i> For: <i>Charlie Perrin</i>	
Title: Environmental Associate		Approval Date: 9/24/08	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com		Conditions of Approval:	
Date: 9/16/08	Phone: 505-326-9866	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Incident # **NRM 0928241779**