

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	Vasaly SWD #2	Facility Type	Salt Water Disposal (SWD) API # 30-045-29936
Surface Owner	Private	Mineral Owner	Private
		Lease No.	Fee

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	22	T30N	R11W	1200'	North	2390'	East	San Juan

Latitude **36.80178° N** Longitude **107.9770° W**

NATURE OF RELEASE

Type of Release - Produced Water (PW)	Volume of Release - 10 BBL PW	Volume Recovered - 8 BBL
Source of Release: Leak in valve	Date and Hour of Occurrence 10/04/08 - Unknown	Date and Hour of Discovery 10/04/08 - 6:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via email	
By Whom? Kristina Kovach	Date and Hour - 10/8/08 - 4:00 p.m.	RCVD OCT 10 '08
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONSV. DIV.	
DIST. 3		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips employee discovered a spill of approximately 10 BBL of produced water at the Vasaly SWD #2 on 10/04/08 due to a leaking valve on the C1 filter pod. Upon discovery, the employee shut in the filter pod and locked out the valve.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids were contained within the lined pit. Approximately 8 BBL of produced water were recovered by vacuum truck and unloaded at the Vasaly SWD #2 facility. To prevent reoccurrence, COPC will install a new valve and monitor for leaks.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kristina L. Kovach</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kristina L. Kovach		Approved by District Supervisor: <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Environmental Associate	Approval Date: 10/10/08	Expiration Date:	
E-mail Address: kristina.l.kovach@conocophillips.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10/8/08	Phone: 505-326-9866		

* Attach Additional Sheets If Necessary

Incident # NRMD0928634560