

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy Inc.	Contact Kim Champlin	
Address #382 County Road 3100, Aztec, NM 87410	Telephone No. (505) 333-3100	
Facility Name Salty Dog #3R (API# 30-045-31274)	Facility Type Salt Water Disposal	
Surface Owner Federal	Mineral Owner	Lease No. NM97843

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	28	30N	14W	850	North	770	East	San Juan

Latitude 36.46228 Longitude 108.20510
Exact Lat/Long of Release

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Approx 125 bbl	Volume Recovered Approx 25 bbl
Source of Release Water Line	Date and Hour of Occurrence 06/20/08, time unknown	Date and Hour of Discovery 06/20/08 3:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell- OCD (via voice message)	
By Whom? Kim Champlin	Date and Hour 06/21/08 1:30 PM	RCVD JUL 2 '08
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* ☐ On 6/20/08 a drop in line pressure caused an NGO to begin looking for a line leak at approximately 9:00am. A paint crew reported to XTO water coming out of the ground on the pipeline right of way at 3:30PM. The leaking water line runs between Bi-Knobs and Salty Dog #3 location. The line was shut in. An estimated 125 barrels of produced water leaked due to a break in the 3" poly SDR11 water line. The spill ran about 135' down the right of way and into a small run off channel off the side of the right of way. It terminated before entering a small unnamed dry arroyo in the area.

Describe Area Affected and Cleanup Action Taken.* ☐ A vac truck was used to recover water from the immediate area of the break. A 6 foot section of 3" poly pipe was removed and another piece of 3" poly pipe was installed using fusion couplings. The damage appeared to have been caused by a rock rubbing a hole into the line. Padding was installed and the line was put back into service at approximately 9:30 PM. An estimated 25 barrels of produced water was recovered at the break. Due to dry weather conditions the rest of the produced water was absorbed into the ground. All notifications were made.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kim Champlin</i>	OIL CONSERVATION DIVISION	
Printed Name: Kim Champlin	Approved by District Supervisor: <i>Bob Bell</i> For: <i>Charlie Perrin</i>	
Title: Environmental Assistant	Approval Date: 7/2/08	Expiration Date:
E-mail Address: Kim_Champlin@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/01/08	Phone: 505-333-3100	

* Attach Additional Sheets If Necessary

Incident # **NM0 0928253030**