<u>District I</u> 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

API#	30-0	×5-313			OPERA		·[☐ Initial Report ☐ Final Report				
Name of Company Devon Energy Production Company, L.P. Address 1751 Hwy 511 Navajo Dam, NM 87419						Contact Steve Zink						
			37419		Telephone No. 505-324-5605							
Facility Name NEBU 442A						Facility Type Gas Well						
Surface Owner BLM Mineral Owner						BLM			Lease No. NM-03358			
				LOCA	TION	OF RE	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North/				t/West Line County			
C	11	31N /	7W	1030]	North	1425	We	est	San Juan		ian
			La	titude		Longitud	le					
						OF REL						
Type of Rele	ase Produc	ed Water	Volume of Release 100 Bbls Volume Recovered 95 Bbls									
		uced Water Ta		Date and Hour of Occurrence Date and Ho 7/24/8 3:00 PM 7/24/8 3:00 I					Iour of Discovery			
Was Immedi	ate Notice (Given?			Whom? Charlie		110 3.1	J J 171				
			Yes [No Not Re	quired							
By Whom? Steve Zink						Date and Hour 7/25/8 2:12 PM						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*						RCVD AUG 4'08						
If a Watercou	ırse was Im	pacted, Descri	ibe Fully.	k					" Simestraft	The Party of the P		-
	45 11		 							DIST	1.3	
Describe Cau	ise of Probl	em and Reme	dial Action	n Taken.*								
measured, pu pump. Througet a warning Therefore, Li in flow lines. tanks were co	imps are sta ughout the d g page befor ease Operate When the ompletely fi oblem. The	rted and water pre the SWD wors did not get water backed alled, and water spill stayed in	r is pumped to ill ESD. It a warning up in the ser started resident the consideration of the	on all four runs. Ved to SWD#2. The SWD #2 causing However, Cygnet as g page. When the flow lines, the faile unning out of the tentainment dike.	e SWD# the tank and pagi Salt Wa ed check top of the	f2 facility way level to rise ing systems hater Disposal k valve on the tanks. 100	s down most of the and eventually Elave been down 2 activated the emee 442A allowed we bbls of produced	se day for SD. (Emer weeks due ergency slavater to flow water ran	a clutch orgency S to comman valve ow back i	change on the hut Down) munication properties, it caused was not the tank tanks before	he main Lease of problent vater to ss. The	charge operators will ons. pressure up two 500 bbl
		and Cleanup A		een.* vas raked after it di	ried up.		-					
regulations a public health should their or or the enviro	II operators or the envi operations h nment. In a	are required to ronment. The nave failed to a	o report and acceptant adequately DCD accep	e is true and compled of the certain rece of a C-141 report investigate and restance of a C-141 report investigate and restance of a C-141 restanc	elease no rt by the emediate	otifications a e NMOCD m e contaminati	nd perform correct parked as "Final Right ion that pose a thruster the operator of	etive action eport" doc eat to ground responsibi	ns for rel es not rel und wate llity for c	eases which ieve the ope r, surface we compliance v	n may en erator of eater, hu with any	ndanger f liabılıty ıman health
Signature: Hurth						OIL CONSERVATION DIVISION						
						Approved by District Supervisor: But Sell For: Charlie Persin						
Title: Produ	ction Superi	intendent		Approval Da	te: 8/4/08	Ex	piration	Date:				
E-mail Addre	ess: Steve.2	Zink@dvn.cor	n			Conditions o				Attached	i 🗌	
	29/8			05-324-5605								
Attach Addi	tional She	ets If Necess	ary			In	adent	# 1	Rms	0928	25	1455