

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	San Juan 32-8 #242A	Facility Type	Gas Well
Surface Owner	Private	Mineral Owner	Federal
		Lease No.	API # 30-045-32119 NM SF-079029

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	4	T31N	R8W	1270'	North	785'	West	San Juan

Latitude 36.92988° N Longitude 107.68651° W

NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release - 13.6 BBL	Volume Recovered - 10.5 BBL
Source of Release: Line break	Date and Hour of Occurrence unknown	Date and Hour of Discovery 7/11/08 - 11:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via email BLM - Kevin Schneider via email	RCVD AUG 20 '08 OIL CONS. DIV.
By Whom? Kristina Kovach	Date and Hour - 7/22/08 - 4:00 p.m.	DIST. 3
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips Company employee discovered a spill of approximately 13.6 BBL of produced water at the San Juan 32-8 #242A on the morning of 7/11/08 due to a line break. The sensing line off of the discharge of the transfer pump cracked from vibration. Upon discovery, the employee shut off the pump.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids were contained within the berm, and approximately 10.5 BBL of produced water were recovered by vacuum truck. The line will be replaced. The affected soils will be monitored to determine if further remediation is necessary. To prevent reoccurrence, COPC will look at alternative ways to plumb in the pressure switch from the discharge pump.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kristina L Kovach</i>	OIL CONSERVATION DIVISION	
Printed Name: Kristina L. Kovach	Approved by District Supervisor: <i>Brandon Powell</i>	For: Charlie Perrin
Title: Environmental Associate	Approval Date: 8/20/08	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/22/08 Phone: 505-326-9866		

* Attach Additional Sheets If Necessary

Incident # NEMD 0928631464