

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Gwen R. Frost
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-326-9549
Facility Name	San Juan 32-9 #12	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-078626
		API #	30-045-10865

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	10	T31N	R09W	990'	South	990'	West	San Juan

Latitude 36.90801° N Longitude 107.77269W

NATURE OF RELEASE



Type of Release – Produced Water & Condensate	Volume of Release – 8 BBL Produced Water & 2 BBL Condensate	Volume Recovered – 6 BBL Produced Water & 2 BBL Condensate
Source of Release: Wellhead	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 5/29/09 – 3:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via e-mail BLM - Kevin Schneider via e-mail	RCVD JUN 4 '09
By Whom? Gwen Frost	Date and Hour – 6/02/09 – 4:00 p.m.	OIL CONS. DIV.
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **On May 29, 2009, a COPC MSO discovered a leak at the 1 inch ball valve on pumping tee on wellhead. Approximately 8 BBL produced water & 2 BBL condensate leaked to the ground. All fluid remained on location. Upon discovery, the MSO shut in the pumping unit & vacuum truck soaked up fluid on ground.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids remained on location. Approximately 6 BBL produced water & 2 BBL of condensate was recovered by vacuum truck. COPC will assess the soils for environmental impact. To prevent reoccurrence, COPC will monitor equipment.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Gwen R. Frost	Approved by District Supervisor:  For: Charlie Perrin	
Title: Environmental Engineer	Approval Date:	Expiration Date:
E-mail Address: gwendolynne.frost@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/02/09 Phone: 505-326-9549		

* Attach Additional Sheets If Necessary

Incident # **n Rnd 0925229932**