

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API# 30-045-33217

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P. O. Box 420, Farmington, NM 87499-0420	Telephone No.	(505)325-1821
Facility Name	Herry Monster SWD #3	Facility Type	

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	NM-17015
---------------	---------	---------------	---------	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	11	24N	11W	1980	North	1700	West	San Juan

Latitude 36.33008 Longitude 108.97504

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	approx 30 bbl	Volume Recovered	approx 0 bbls
Source of Release	Underground water line broke	Date and Hour of Occurrence	8/5/08 @ approx 5:00 p.m.	Date and Hour of Discovery	8/5/08 @ approx 5:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Aztec Office NMOCD - Brandon Powell & BLM Farmington Office		
By Whom?	Rodger Mullins	Date and Hour	8/6/08 @ 8:00 a.m. - Brandon		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RCVD AUG 7 '08

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV.

DIST. 3

Describe Cause of Problem and Remedial Action Taken.*

Underground water line broke causing the area to flow onto location and off location approximately 150'. Spreading gypsum on affected area.

Describe Area Affected and Cleanup Action Taken.*

Water soaked into soil. Spreading gypsum on affected area. Further cleanup will be pending upon test results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodger V. Mullins</i>		OIL CONSERVATION DIVISION	
Printed Name: Rodger Mullins		Approved by District Supervisor: <i>Bob Pell</i> For: <i>Charlie Perrin</i>	
Title: Production Foreman		Approval Date: 8/7/08	Expiration Date:
E-mail Address: rmullins@duganproduction.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 6, 2008 Phone: (505)325-1821			

* Attach Additional Sheets If Necessary

Incident # NMO 0908156155

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P. O. Box 420, Farmington, NM 87499-0420	Telephone No.	(505)325-1821
Facility Name	Herry Monster SWD #3	Facility Type	

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	NM-17015
---------------	---------	---------------	---------	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	11	24N	11W	1980	North	1700	West	San Juan

Latitude 36.33008 Longitude 108.97504

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	approx 30 bbl	Volume Recovered	approx 0 bbls
Source of Release	Underground water line broke	Date and Hour of Occurrence	8/5/08 @ approx 5:00 p.m.	Date and Hour of Discovery	8/5/08 @ approx 5:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Aztec Office NMOCD – Brandon Powell & BLM Farmington Office		
By Whom?	Rodger Mullins	Date and Hour	8/6/08 @ 8:00 a.m. - Brandon		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Underground water line broke causing the area to flow onto location and off location approximately 150'. Spreading gypsum on affected area.

Describe Area Affected and Cleanup Action Taken.*

Water soaked into soil. Spreading gypsum on affected area. Further cleanup will be pending upon test results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Rodger v. Mullins</i>	Approved by District Supervisor:	
Printed Name: Rodger Mullins	Approval Date:	Expiration Date:
Title: Production Foreman	Conditions of Approval:	
E-mail Address: rmullins@duganproduction.com	Attached <input type="checkbox"/>	
Date: August 6, 2008 Phone: (505)325-1821		

* Attach Additional Sheets If Necessary