

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Williams Production	Contact Michael K. Lane	
Address PO Box 640	Telephone No. 505-634-4219	
Facility Name Jicarilla 92 #016 (API: 30-039-22500)	Facility Type Well Site	
Surface Owner Tribal	Mineral Owner Tribal	Lease No.

LOCATION OF RELEASE

Unit Letter E	Section 30	Township 27 N	Range 03W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
-------------------------	----------------------	-------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water & Condensate	Volume of Release ~20 bbl	Volume Recovered ~None
Source of Release Storage Tank Frozen drain valve	Date and Hour of Occurrence 3/30/09 >12:00 AM	Date and Hour of Discovery Same
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD APR 10 '09	
By Whom?	Date and Hour OIL CONS. DIV.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. DIST. 3	

If a Watercourse was Impacted, Describe Fully. **No water course reached.**



Describe Cause of Problem and Remedial Action Taken.

Drain valve to storage tank cracked due to freezing conditions. Leaked water and condensate to ground immediately adjacent to tank. Water and product soaked into soils.

Upon discovery, 5 gallon bucket set under valve and valve packing tightened until tank could be drained and valve replaced. Arrangements to assess extent of contamination, excavate contaminated soils for offsite disposal, backfill excavation being scheduled. Upon completion revised report with sample results and disposal documents will be submitted.

Describe Area Affected and Cleanup Action Taken. See above.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Michael K. Lane		Approved by District Supervisor:  For: Charlie Perrin	
Title: SJB EH&S Specialist		Approval Date: 4/10/09	Expiration Date:
E-mail Address: myke.lane@williams.com		Conditions of Approval:	
Date: 4/08/09 Phone: (505) 330-3198		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Incident # 11 RMD 0924633561