

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report



Name of Company	ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30 <sup>th</sup> St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	San Juan 28-7 #194F	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-078471
		API # 30-039-30200	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	21	T28N	R7W	1015'	North	1495'	East	Rio Arriba

Latitude 36.65114° N Longitude 107.57500° W

#### NATURE OF RELEASE

Type of Release - <b>Condensate</b>	Volume of Release - <b>25 BBL</b>	Volume Recovered - <b>23 BBL</b>
Source of Release: <b>Pit overflow</b>	Date and Hour of Occurrence	Date and Hour of Discovery <b>4/11/08 - 3:00 p.m.</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>OCD - Brandon Powell via phone &amp; email</b> <b>BLM - Kevin Schneider via email</b>	
By Whom? <b>Kristina Kovach</b>	Date and Hour - <b>4/14/08 - 4:00 p.m.</b>	<b>RCVD APR 28 '08</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>OIL CONS. DIV.</b> <b>DIST. 3</b>	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <b>A ConocoPhillips Company employee discovered a condensate spill of approximately 25 BBL at the San Juan 28-7 #194F on the afternoon of 4/11/08. The spill occurred when a dump valve on the separator malfunctioned and pushed condensate to the water pit.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>All of the spilled fluids were contained within the berm. Approximately 23 BBL of condensate were recovered by vacuum truck and returned to the production tank. The affected soils will be excavated. The valve was replaced. To prevent reoccurrence, COPC will check the dump valves on the separator regularly.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Kristina L. Kovach</b>	Approved by District Supervisor:  For: Charlie Perrin	
Title: <b>Environmental Associate</b>	Approval Date: <b>4/28/09</b>	Expiration Date:
E-mail Address: <b>kristina.l.kovach@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>4/14/08</b> Phone: <b>505-326-9866</b>		

\* Attach Additional Sheets If Necessary

Incident # **NRMD0929649696**