

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30 045 05343

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Elm Ridge Exploration CO LLC	Contact: Amy Mackey
Address: PO BOX 156 Bloomfield, NM 87413	Telephone No. 505-632-3476 ext. 201
Facility Name: Carson Unit 18-24	Facility Type: Injection Well

Surface Owner: The Navajo Nation	Mineral Owner	Lease No. 14-20-603-1285
----------------------------------	---------------	--------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	18	25N	11W	660'	South	1930'	West	San Juan

Latitude: 36.39564 Longitude: -108.04689

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 410 BBLs	Volume Recovered: 400 BBLs
Source of Release: Split pipe	Date and Hour of Occurrence: 5-5-08 Time	Date and Hour of Discovery: 5-5-08 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin	
By Whom? Amy Mackey	Date and Hour: 2-1-08 at 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCUD NOV 13 '08

OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*

No, it was contained on location.



Describe Cause of Problem and Remedial Action Taken.*

There was a leak in the pipe line about 10' from the wellhead. It was completely contained on location. We recovered 400 bbls of water and a 10 bbl mixture of oil and dirty iron sulfite water. We had Frank's Oilfield, Quality, and C & J Trucking cleaning up the spill.

Describe Area Affected and Cleanup Action Taken.*

Recovered all liquid and contaminated soil and took to Envirotech's land farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Amy Mackey		Approved by District Supervisor:  For: Charlie Perrin	
Title: Administrative Manager		Approval Date: 5/13/08	Expiration Date:
E-mail Address: amackey1@elmridge.net		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5-12-08 Phone: 505-632-3476 ext 201			

* Attach Additional Sheets If Necessary

Incident # n/pmd 0929649409