

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>XTO Energy Inc.</b>	Contact <b>Kim Champlin</b>	
Address <b>#382 County Road 3100 Aztec, NM 87410</b>	Telephone No. <b>(505) 333-3100</b>	
Facility Name <b>Canyon #7E (API 30-045-29710)</b>	Facility Type <b>Gas (Dakota)</b>	
Surface Owner <b>Navajo</b>	Mineral Owner	Lease No. <b>NOOC14203618</b>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>G</b>	<b>15</b>	<b>25N</b>	<b>11W</b>	<b>1500</b>	<b>North</b>	<b>1500</b>	<b>East</b>	<b>San Juan</b>

Latitude 36.40411 Longitude 107.98686

**NATURE OF RELEASE**

Type of Release <b>Produced Oil</b>	Volume of Release <b>Approx 6 bbl</b>	Volume Recovered <b>Approx 4 bbl</b>
Source of Release <b>Pressure Valve at Wellhead</b>	Date and Hour of Occurrence <b>01/20/09, Time Unknown</b>	Date and Hour of Discovery <b>01/20/08 4:30PM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>RCVD FEB 5 '09 OIL CONSV. DIV DIST. 3</b>	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <input type="checkbox"/> An XTO Employee arrived on location and discovered produced oil on the ground around the wellhead and pumping unit. The well was immediately shut in and upon investigation it was determined that the tubing back pressure valve on the pressure gauge had some water build up inside the valve that froze and caused it to break. An estimated 6 barrels of produced oil was released and 4 barrels recovered.		
Describe Area Affected and Cleanup Action Taken.* The well was immediately shut in and vac trucks were dispatched. An estimated 4 barrels of standing produced oil was recovered. A roustabout crew disposed of approximately 25 yards of contaminated soil at a state permitted facility. The pressure valve was repaired and pressure tested before the well was put back online. The release was contained to the immediate area around the wellhead and pumping unit and nothing left location.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Kim Champlin</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Kim Champlin</b>	Approved by District Supervisor: <i>[Signature]</i>	For: <b>Charlie Perrin</b>
Title: <b>Sr. Environmental Representative</b>	Approval Date: <b>2/5/09</b>	Expiration Date:
E-mail Address: <b>Kim_Champlin@xtoenergy.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>02/02/09</b>	Phone: <b>505-333-3100</b>	

\* Attach Additional Sheets If Necessary

nBP0918933399