

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

API# 30-045-33639

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy	Contact	Robert Jordan
Address	1751 HWY. 511	Telephone No.	505-320-1395
Facility Name	NEBU 245	Facility Type	Gas Well
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	31N	7W	1095	South	730	West	San Juan

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Condensate	Volume of Release	45 BBLs	Volume Recovered	45 BBLs
Source of Release:	Tank	Date and Hour of Occurrence:	UNK	Date and Hour of Discovery	7/3/09 12:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell		
By Whom?	Robert Jordan	Date and Hour	7/6/09 1300		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RCVD JUL 8 '09

OIL CONS. DIV.  
DIST. 3

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The Conventional well 245 water is dumping into the 474 CBM system and the check valve failed causing the water from the 474 to fill the tank on the 245 overflowing it 45 bbls. Of condensate.

Describe Area Affected and Cleanup Action Taken.\*

A 20' X 60' area that has spray liner in place no fluid has contacted the soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name: Robert A. Jordan	Approved by District Supervisor:  For: Charles Perrin		
Title: Production Foreman	Approval Date: 7-8-09	Expiration Date:	
E-mail Address: Robert.jordan@dmv.com	Conditions of Approval:	Attached <input type="checkbox"/>	

Incident #1 RMD 0924747152

