



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(~~TA~~ OR UIC)

Date of Test Jan 21, 2004 Operator Burlington Resources API # 30-0 30-23501

Property Name San Juan 30-6 Unit Well # 1124 Location: Unit A Sec 26 Twn 30 Rge 6

Land Type:

State _____
Federal X _____
Private _____
Indian _____

Well Type:


Water Injection _____
Salt Water Disposal X _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): No TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. 400 Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. 520
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 370 psi. for 30 mins. Test passed/~~failed~~

REMARKS:




By James G. Stinson
(Operator Representative)

Witness Bruce Martin
(NMOCD)

James G. Stinson
(Position) Sr. Operator

Revised 02-11-02



Graphic Controls
SS.
CHART NO. MC MP-1000-1HR
1/21/04
METER _____ TAKEN OFF _____
CHART PUT ON _____
LOCATION _____
REMARKS *Durlington Res.*
SJ 30-6 #112/SWD
API # 30-039-23501

JAN 2004
4803