UNITED STATES

DEPARTMENT OF THE INTERIOR

RECEIVED

Sundry Notices and Repo	orts on Wells 22 FH 1: 47
Type of Well GAS	5. Lease Number ()70 Farmington, NM sp078128 6. If Indian, All. or Tribe Name
	7. Unit Agreement Nam
Name of Operator	
BURLINGTON RESOURCES OIL & GAS COMPAN	
Address & Phone No. of Operator	8. Well Name & Number
PO Box 4289, Farmington, NM 87499 (505)) 326-9700
Location of Well, Footage, Sec., T, R, M 990'FNL,990'FEL, Sec.28, T-30-N, R-9-W, N	
	11. County and State San Juan Co, NM
. CHECK APPROPRIATE BOX TO INDICATE NATURE	E OF NOTICE, REPORT, OTHER DATA
Type of Submission Notice of Intent Abandon	Type of Action ment Change of Plans
Recomp.	letion New Construction
X_Subsequent ReportPlugging Casing	Back Non-Routine Fracturing Repair Water Shut off
	Macer blac off
	g CasingConversion to Injection Tubing Repair
	Tubing Repair
X_Other . Describe Proposed or Completed Operat: 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow	Tubing Repair
X_Other . Describe Proposed or Completed Operat: 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow	Tubing Repair ions W/tbg. SDFN. & Clean out to PBTD @ 4905'.TOOH. TIH W/156 J
X_Other . Describe Proposed or Completed Operation 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow	Tubing Repair ions W/tbg. SDFN. & Clean out to PBTD @ 4905'.TOOH. TIH W/156 J
X_Other . Describe Proposed or Completed Operation 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow	Tubing Repair ions W/tbg. SDFN. & Clean out to PBTD @ 4905'.TOOH. TIH W/156 J
X_Other Describe Proposed or Completed Operation 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow	Tubing Repair ions W/tbg. SDFN. & Clean out to PBTD @ 4905'.TOOH. TIH W/156 J landed @ 4841'. ND BOP, NU WH. RD. Rig Releas
X_Other . Describe Proposed or Completed Operat: 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow	Tubing Repair ions W/tbg. SDFN. & Clean out to PBTD @ 4905'.TOOH. TIH W/156 J landed @ 4841'. ND BOP, NU WH. RD. Rig Releas
X_Other . Describe Proposed or Completed Operat: 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow	Tubing Repair ions W/tbg. SDFN. Clean out to PBTD @ 4905'.TOOH. TIH W/156 J landed @ 4841'. ND BOP, NU WH. RD. Rig Releas ACCEPTED FOR RECORD DEC 3 1 2003 FARMINGTON FIEED OFFICE BY
Describe Proposed or Completed Operat: 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow 2 3/8" 4.7# J-55 Eue tbg	Tubing Repair ions W/tbg. SDFN. Clean out to PBTD @ 4905'.TOOH. TIH W/156 J landed @ 4841'. ND BOP, NU WH. RD. Rig Releas ACCEPTED FOR RECORD DEC 3 1 2003 FARMINGTON FIEED OFFICE BY
Describe Proposed or Completed Operat: 10/27/03 MIRU. ND WH, NU BOP. TOOH 10/28/03 TIH tag up @ 4815'. Blow 2 3/8" 4.7# J-55 Eue tbg	Tubing Repair ions W/tbg. SDFN. Clean out to PBTD @ 4905'.TOOH. TIH W/156 J landed @ 4841'. ND BOP, NU WH. RD. Rig Releas DEC 3 1 2003 FARMINGTON FIEED OFFICE BY Regulatory Assistant Date 12/18/03 fsb