

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30039 08149

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: XTO Energy Inc	Contact: Darrin Steed
Address: 2700 Farmington Ave, Bldg K, Ste 1	Telephone No.: 505-324-1090
Facility Name: Jicarilla Apache #11	Facility Type: Gas well

Surface Owner: Jicarilla Apache Nation	Mineral Owner: BLM & Jicarilla Apache Nation	Lease No.: Tract 251 Contract 154
--	--	-----------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 28	Township 26N	Range 5W	Feet from the 1040'	North/South Line South	Feet from the 800'	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	-------------	------------------------	---------------------------	-----------------------	------------------------	----------------------

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 150 bbls	Volume Recovered: 142 bbls
Source of Release: Stock tank	Date and Hour of Occurrence 11/23/02 @ 7:00 a.m.	Date and Hour of Discovery 11/23/02 @ 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? Kevin Harris	Date and Hour: 11/23/02 @ 11:32 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The 1" ball valve on the roll line for tank #GEC 4452 came off causing 150 bbls of oil to be emptied into the bermed battery. A vacuum truck picked up 142 bbls and put it into the second tank. The roll line was removed and the taps on both tanks were bull plugged.

Describe Area Affected and Cleanup Action Taken.*

150 bbls of oil emptied into the bermed tank battery. No product left the area or got onto the location. BLM, NMOCD, Blagg Engineering and the Jicarilla Apache Nation were notified. Remediation and cleanup is ready pending approval of Jicarilla Apache Environmental Protection Office.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Darrin Steed</i>	OIL CONSERVATION DIVISION	
Printed Name: Darrin Steed	Approved by <i>Denny Foust</i> for Frank Chavez	
Title: Regulatory Supervisor	Approval Date: 12/06/02	Expiration Date:
Date: 12/2/02	Phone: 324-1090	Conditions of Approval: Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DGF 0232936500