

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico


Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141
Originated 2/13/97Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

OPERATOR

Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	Gregg Wurtz
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9537
Facility Name:	SAN JUAN 29-7 UNIT 113	Facility Type:	Gas Well

Surface Owner:	Federal	Mineral Owner:	Federal	Lease Number:	NMSF-078945
----------------	---------	----------------	---------	---------------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: Rio Arriba
B	29	029N	007W	945	north	2300	east	

NATURE OF RELEASE

Type of Release:	Condensate	Volume of Release:	40 BBLs.	Volume Recovered:	0 BBLs.
Source of Release:	Storage tank	Date and Hour of Occurrence:	1/23/2002 7:00:00 AM	Date and Hour of Discovery:	1/28/2002 10:45:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom?	Denny Foust		
By Whom?	Gregg Wurtz	Date and Hour:	1/28/2002 11:30:00 A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Frozen drain valve (old cast iron design). Excavate soil under drain valve to bedrock and landfarm on location.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Spill contained within the berm. Localized to an area directly under the drain valve down to bedrock..

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name:	Gregg Wurtz	Approved by	<i>Denny Foust</i>
Title: Environmental Representative		District Supervisor:	for Frank Chavez
Date: 1/28/02	Phone: (505) 326-9841 or 326-9842	Approval Date: 01/30/02	Expiration Date:
Conditions of Approval:		Attached: <input type="checkbox"/>	

NDGF0202843636