

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division


2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.



Release Notification and Corrective Action

30 039 21865

OPERATOR

Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	Ed Hasely
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9841
Facility Name:	SAN JUAN 28-5 UNIT	Facility Type:	Gas Well

Surface Owner:	Federal	Mineral Owner:	Federal	Lease Number:	NMSF-079250-
----------------	---------	----------------	---------	---------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: Rio Arriba
P	11	028N	005W	1180	South	470	East	

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	20 BBLS.	Volume Recovered:	10 BBLS.
Source of Release:	Open Top Steel Tank	Date and Hour of Occurrence:	1/23/2002	Date and Hour of Discovery:	1/23/2002
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?			
By Whom?					
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

A corrosion hole in the open top steel tank allowed the contents (approximately 20 bbls of produced water) of the tank to leak out into the bermed area.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

A vacuum truck recovered approximately 10 bbls of the produced water. The tank was replaced. The impacted soils will be raked to break up any crust that may form.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Ed Hasely</i>	OIL CONSERVATION DIVISION	
Printed Name:	Ed Hasely	Approved by	<i>Denny Hunt</i>
Title: Environmental Representative		District Supervisor:	<i>for Frank Chavez</i>
Date: 1/28/02	Phone: (505) 326-9841 or 326-9842	Approval Date:	01/30/2002
		Expiration Date:	
		Conditions of Approval:	Attached: <input type="checkbox"/>

n DGFO 20305-6349

