

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 23035

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Williams Energy	Contact <input type="checkbox"/> Roxanne Roberts
Address One Williams Center MD 26-5	Telephone No. <input type="checkbox"/> (918) 573-0195
Facility Name Rosa 94 SWD	Facility Type <input type="checkbox"/> salt water disposal well

Surface Owner USFS/BLM	Mineral Owner	Lease No. <input type="checkbox"/>
------------------------	---------------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section 16	Township 31 N	Range 5 W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
-------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	----------------------

NATURE OF RELEASE

Type of Release produced water	Volume of Release 50 barrels	Volume Recovered <input type="checkbox"/> 25 barrels
Source of Release check valve	Date and Hour of Occurrence 9/10/02 9:30 A.M.	Date and Hour of Discovery <input type="checkbox"/> 9/10/02 9:30 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? <input type="checkbox"/> Olivia Engle	Date and Hour <input type="checkbox"/> 9/10/02 4:00 P.M. (within 24 hours)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A foreign object was holding the check valve open allowing a flow of water. The object was removed causing the flow to stop.

Describe Area Affected and Cleanup Action Taken.*

The area affected by the problem includes land contained by the berm and a small area directly outside of the berm. The water was contained on-site. 25 of the 50 barrels was recovered using a vacuum and will be used in drilling.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Roxanne Roberts</u>		OIL CONSERVATION DIVISION	
Printed Name: Roxanne Roberts		Approved by <input type="checkbox"/> District Supervisor: <u>Denny Foust</u> <u>for Frank Chavez</u>	
Title: <u>EHS Coordinator</u>		Approval Date: <u>9/16/02</u>	Expiration Date:
Date: 9/11/2002	Phone: (918) 573-0195	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

N 06F0225437499