

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-24236

OPERATOR

Initial Report x Final Report

Name of Company: Devon Energy Production Co. L.P.	Contact <input type="checkbox"/> Kyle Beebe
Address: PO Box 6459 Navajo Dam N.M 87419	Telephone No. <input type="checkbox"/> 324-5600
Facility Name: Simms Mesa SWD	Facility Type: SWD

Surface Owner: State	Mineral Owner: BLM	Lease No. <input type="checkbox"/> SF 079001
----------------------	--------------------	--

LOCATION OF RELEASE

Unit Letter	Section 10	Township 30N	Range 7W	Feet from the 1450	North/South Line FNL	Feet from the 790	East/West Line FWL	County Rio Arriba
Longitude-W 107 33 9				Latitude-N 36 49 8				

NATURE OF RELEASE

Type of Release: Salt Water	Volume of Release 190 bbls.	Volume Recovered <input type="checkbox"/> 180 bbls.
Source of Release: Produced Water	Date and Hour of Occurrence During night of 2/3/07	Date and Hour of Discovery <input type="checkbox"/> 2/4/07 12:10 p.m.
Was Immediate Notice Given? Not Required X Yes (within 24 hrs) <input type="checkbox"/> No <input type="checkbox"/>	If YES, To Whom? Brandon Powell	RCVD FEB16'07 OIL CONS. DIV. DIST. 3
By Whom? <input type="checkbox"/>	Date and Hour <input type="checkbox"/> 2/5/07	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* O-ring seal on secondary filter pot went bad due to chemical reaction caused water to leak out

Describe Area Affected and Cleanup Action Taken.*

Water Inside dike water truck vacuumed water up off of frozen ground put back Into tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Steve Zwick	Approved by <input type="checkbox"/> District Supervisor: Brandon Powell For: Charlie Perrin		
Title: Superintendent	Approval Date: 2-16-07	Expiration Date:	
Date: 2/13/7 Phone: 505-320-0677	Conditions of Approval:		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NBP 0711033975