

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30-039-24236

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Steve Zink	
Address P.O Box 6459 Navajo Dam N.M 87419	Telephone No. 505-324-5605	
Facility Name Sims Mesa SWD	Facility Type Salt Water Disposal	
Surface Owner State	Mineral Owner Federal	Lease No. SF 079001

LOCATION OF RELEASE

Unit Letter E	Section 10	Township 30N	Range 7W	Feet from the 1450'	North/South Line North line	Feet from the 790'	East/West Line West line	County Rio Arriba
------------------	---------------	-----------------	-------------	------------------------	--------------------------------	-----------------------	-----------------------------	----------------------

Latitude N36 49.8 Longitude W107 33.9

NATURE OF RELEASE

Type of Release Salt Water	Volume of Release 20 bbl	Volume Recovered 15 bbl
Source of Release Tank ran over	Date and Hour of Occurrence 1-22-08 11:30 AM	Date and Hour of Discovery 1-22-08 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Steve Zink	Date and Hour 1-23-08 10:55 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD JAN 25 '08
OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Tank header froze off allowing settlement tank to run over. We lit tank fires and got header rearticulating with hot glycol

Describe Area Affected and Cleanup Action Taken.*

Inside the tank berm 150' x 30' ground covered with water. Had water truck suck up 15 bbl Waiting to dry up to work dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Zink	Approved by District Supervisor:  For: Charlie Perrin	
Title: Production Superintendent	Approval Date: 1-25-08	Expiration Date:
E-mail Address: Steve.Zink@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/24/8 Phone (505) 324-5605		

* Attach Additional Sheets If Necessary

MBP0804351945