

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30 039 24863

Name of Company Williams Energy		Contact Roxanne Roberts	
Address One Williams Center MD 26-5		Telephone No. (918) 573-0195	
Facility Name Rosa 310		Facility Type: coal bed methane well	
Surface Owner USFS/BLM		Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section 26	Township 31 N	Range 4 W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
-------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	----------------------

NATURE OF RELEASE

Type of Release produced water from CBM well	Volume of Release: 9 barrels	Volume Recovered: 0 barrels
Source of Release:	Date and Hour of Occurrence 9/24/2002 11:00 A.M.	Date and Hour of Discovery 9/24/2002 @ 11:00 A.M.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Water was being evaporated from the reserve pit. During this process some of the water collected in a gopher hole that was connected by a tunnel to another hole. The water that collected in the first hole traveled through the tunnel and out of the second hole. After leaving the second hole the water traveled off-site approximately 200 yards and stopped at the edge of a dry wash. Areas were diked to prevent further release.

Describe Area Affected and Cleanup Action Taken.\*

The areas affected include the gopher holes and tunnel and a path extending from the second hole to the edge of the dry wash.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Roxanne Roberts</u>		OIL CONSERVATION DIVISION	
Printed Name: Roxanne Roberts		Approved by <input type="checkbox"/> District Supervisor: <u>Denny Faint for Frank Chavez</u>	
Title: <u>EH&amp;S Coordinator</u>	Approval Date: <u>11/05/02</u>	Expiration Date:	
Date: <u>10/1/02</u> Phone: (918) 573-0195	Conditions of Approval:	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

1106F0230142887