

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9829
Facility Name	San Juan 29-6 Unit #262	Facility Type	Gas Well
Surface Owner	Private	Mineral Owner	Federal
		Lease No.	SF-080379-A

API # 30-039-25090

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	21	T29N	R6W	814'	North	951'	East	Rio Arriba

Latitude 36.71609° N Longitude 107.46196° W

NATURE OF RELEASE

Type of Release – Produced water	Volume of Release – 11 BBL	Volume Recovered – none
Source of Release: Produced water tank overfilled	Date and Hour of Occurrence 11/17/07	Date and Hour of Discovery 11/17/07
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – OCD – via email Mark Kelly – BLM – via email	RCVD NOV 20 07 OIL CONS. DIV. DIST. 3
By Whom? Monica D. Johnson	Date and Hour – 11/19/07 – 1:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A spill of 11 BBL produced water occurred at the San Juan 29-6 Unit #262 on 11/17/07, due to the produced water tank overfilling. The tank level had been called in to the trucking company, but the trucking company did not pull the load in a timely manner. All fluids remained within the bermed area, but no fluids were recoverable.**

Describe Area Affected and Cleanup Action Taken.* **All fluids remained within the bermed area and affected an area 38' x 30' x 10" deep (max.), but no fluids were recoverable. The impacted soil was allowed to dry and was raked to promote rehabilitation.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Johnson</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor: <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Sr. Environmental Scientist	Approval Date: 11/20/07	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/19/07 Phone: 505-326-9829		

* Attach Additional Sheets If Necessary

nBP0734042108