

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

API# 30-039-253.00

Name of Company <b>Williams Production</b>		Contact <b>Michael K. Lane</b>	
Address <b>PO Box 640</b>		Telephone No. <b>505-634-4219</b>	
Facility Name <b>Chicosa 36-1</b>		Facility Type <b>Well Site</b>	

Surface Owner <b>USFS</b>	Mineral Owner <b>BLM</b>	Lease No.
---------------------------	--------------------------	-----------

**LOCATION OF RELEASE**



Unit Letter <b>D</b>	Section <b>36</b>	Township <b>31 N</b>	Range <b>04W</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Rio Arriba</b>
-------------------------	----------------------	-------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>~6 bbl</b>	Volume Recovered <b>~0 bbl</b>
Source of Release <b>Produced Water Tank – damaged swedge leaked.</b>	Date and Hour of Occurrence <b>&lt;4/11/07 12:00 PM</b>	Date and Hour of Discovery <b>Same</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>RCVD APR16'07</b>	
By Whom?	Date and Hour <b>OIL CONS. DIV.</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>DIST. 3</b>	
If a Watercourse was Impacted, Describe Fully.		
Describe Cause of Problem and Remedial Action Taken. <b>Produced water leaked from damaged swedge to tank. Contained within secondary containment. Swedge repaired.</b>		
Describe Area Affected and Cleanup Action Taken. <b>As well pad and containment to be sterilized during production life of well, will reclaim when well P&amp;A'd. No further action being taken at this time.</b>		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Michael K. Lane</b>	Approved by District Supervisor:  For: <b>Charlie Perrin</b>	
Title: <b>SJB EH&amp;S Specialist</b>	Approval Date: <b>4-16-07</b>	Expiration Date:
E-mail Address: <b>myke.lane@williams.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>4/16/07</b> Phone: <b>(505) 330-3198</b>		

\* Attach Additional Sheets If Necessary

HB0719 339482