


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999



Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

30 039 25954

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CONOCO INC.	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name PORK CHOP 27-1E	Facility Type PRODUCTION FACILITY

Surface Owner BLM	Mineral Owner BLM	Lease No. NMSF078048
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 27	Township 26N	Range 7W	Feet from the 1815	North/South Line FNL	Feet from the 1160	East/West Line FWL	County RIO ARRIBO
------------------	---------------	-----------------	-------------	-----------------------	-------------------------	-----------------------	-----------------------	-------------------

NATURE OF RELEASE

Type of Release PRODUCED OIL	Volume of Release 8 BBLS OIL	Volume Recovered 7 BBLS OIL
Source of Release 2 INCH OIL TANK DRAIN LINE	Date and Hour of Occurrence 2/12/02 UNKNOWN	Date and Hour of Discovery 2/14/02 10:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* INSTALLED VALVE AT THE END OF DRAIN LINE TO CONTROL LEAKING TANK DRAIN VALVE. THIS CAUSED THE LINE INBETWEEN THE TWO VALVES TO FREEZE AND CRACK. PICKED UP ALL FREE STANDING FLUID.

Describe Area Affected and Cleanup Action Taken.* 2 FEET AROUND OIL TANK 1 INCH DEEP. AFFECTED SOIL WILL BE REMOVED AND PROPERLY REMEDATED, NEW SOIL WILL BE ADDED.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: GARY LEDBETTER	Approved by District Supervisor:	
Title: SHEAR SPECIALIST	Approval Date: 02/25/02	Expiration Date:
Date: 2/20/02 Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

N DG F0205656265