

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact Monica D. Johnson
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-326-9829
Facility Name San Juan 27-5 Unit #143M	Facility Type Gas Well
Surface Owner Federal	Mineral Owner Federal
Lease No. NMSF-079394	

LOCATION OF RELEASE

Unit Letter C	Section 34	Township T27N	Range R5W	Feet from the 1000'	North/South Line North	Feet from the 1850'	East/West Line West	County Rio Arriba
-------------------------	----------------------	-------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	-----------------------------

Latitude 36.53536° Longitude 107.34856°



NATURE OF RELEASE

Type of Release – 2% KCl water	Volume of Release – 40 BBL	Volume Recovered – none
Source of Release: Steel rig pit leak	Date and Hour of Occurrence 4/14/07?	Date and Hour of Discovery 4/16/07
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – OCD – via phone on 4/20/07 Mark Kelly – BLM – via email	
By Whom? Monica D. Johnson	Date and Hour – 4/20/07 – 2:00 p.m.	RCOD APR24'07 OIL CONS. DIV.
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. DIST. 3	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* **The rig crew discovered a KCl water spill of 40 BBL at the San Juan 27-5 Unit #143M on the morning of 4/16/07, due to the steel rig pit leaking from a pinhole leak due to corrosion. The leak probably occurred over the weekend. All fluids remained on location, with none recoverable.**

Describe Area Affected and Cleanup Action Taken.* **All fluids remained on location, with none recoverable. The location will be bladed and raked for remediation. The steel rig pit was emptied and removed / replaced.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor:  For: Charlie Perrin	
Title: Environmental Specialist	Approval Date: 4-24-07	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/20/07 Phone: 505-326-9829		

* Attach Additional Sheets If Necessary

NBP0719342020