


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30 039 26741

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Williams Energy	Contact Roxanne Roberts
Address One Williams Center MD 26-5	Telephone No. (918) 573-0195
Facility Name Rosa 361	Facility Type: coal bed methane well

Surface Owner USFS/BLM	Mineral Owner	Lease No.
------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 16	Township 31 N	Range 5 W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
-------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	----------------------

NATURE OF RELEASE

Type of Release produced water from CBM well	Volume of Release: 5 barrels	Volume Recovered: 4.5 barrels
Source of Release: <i>Tank over topping</i>	Date and Hour of Occurrence 9/15/2002 12:50 P.M.	Date and Hour of Discovery 9/15/2002 @ 12:50 P.M.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The water tank at the Rosa 361 site was overflowing. In order to stop the spill, the water from the tank was removed.

Describe Area Affected and Cleanup Action Taken.*

The area affected by the spill was contained within the secondary containment. 4.5 of the 5 barrels spilled were recovered on site. Dawn Trucking was called into remediate the spill area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Roxanne Roberts</i>	OIL CONSERVATION DIVISION	
Printed Name: Roxanne Roberts	Approved by <input type="checkbox"/> District Supervisor: <i>Denny Faint for Frank Chavez</i>	
Title: <i>EHS Coordinator</i>	Approval Date: <i>10/07/02</i>	Expiration Date:
Date: <i>9/30/02</i> Phone: (918) 573-0195	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

10GF0228131674