District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 **District IV** 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

| Release Notification and Corrective Action | | | | | | | | | | |
|--|-----------|---------------|--------------|---------------|-----------|--|--|--|-------------------|--------------------|
| API#30-039-26949 | | | | | | OPERATOR | | | | |
| | | | | | | Contact Michael K. Lane | | | | |
| | | | | | | Telephone No. 505-634-4219 ☐ Facility Type Well Site □ | | | | |
| Surface Owner BLM Mineral Owner | | | | | | | | | | |
| Surface Owner BLIV Mineral Owner | | | | | | BLM Lease No. □ | | | | |
| Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County | | | | | | | | | | |
| Unit Letter K | Section 8 | Township 31 N | Range 05W | Feet from the | North | h/South Line Feet from the Eas | | | Line | County Rio Arriba□ |
| | | | titude | | Longitude | | | | | |
| NATURE OF RELEASE | | | | | | | | | | |
| Type of Release Produced Water | | | | | | | | | Recovered ~25 bbi | |
| Source of Release Produced Water Tank | | | | | | <1/24/08 09:15 AM Same | | | Hour of Discovery | |
| Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required | | | | | | \$47 ft de Et. 62 t 87 t 47 d 47 d | | | | |
| By Whom? Myke Lane | | | | | | Date and Hour OIL CONS. DIV. | | | | |
| Was a Watercourse Reached? ☐ Yes ☒ No | | | | | | If YES, Volume Impacting the Watercourse. DIST. 3 | | | | |
| If a Watercourse was Impacted, Describe Fully. | | | | | | | | | | |
| Describe Cause of Problem and Remedial Action Taken. Well was brought back on after being shut in. There is a water pump installed on location that pumps water to the Rosa 94 disposal. The water pump malfunctioned letting the tank reach capacity and releasing 30 Barrels into the berm. Contained within secondary containment and on location. Well shutin until tank and containment drained. | | | | | | | | | | |
| Describe Area Affected and Cleanup Action Taken. Recovered water with vac. truck. Repaired pump and monitor for proper function. Saturated soil conditions (inclement weather) likely to prevent significant produced water impact. As well pad and containment to be sterilized during production life of well, will reclaim when well P&A'd. No further action being taken at this time. | | | | | | | | | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | | | | | | | | | |
| Signature: Approved by District Supervisor: Franch Pull For: Charlie Printed Name: Michael K. Lane | | | | | | | | | | |
| Printed Name: Michael K. Lane | | | | | | 11 pange voo rena | | | | |
| Title: SJB EH&S Specialist | | | | | | Approval Date: 1-30-08 Expiration Date | | | Date: | |
| E-mail Address: myke.lane@wlliams.com | | | | | | Conditions of Approval: | | | | Attached |
| Date: 1/2 | 9/08 | Phone: | 30-3198 | | | | | | | |