

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 89655

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Playa Minerals & Energy, Inc.	Contact <input type="checkbox"/> Ken Jackson
Address 650 N. Sam Houston Pkwy. E. Suite 500 Houston, Texas 77060	Telephone No. <input type="checkbox"/> (281) 931-3800
Facility Name Northeast Hogback Unit #37	Facility Type <input type="checkbox"/> Oil Lease

Surface Owner Navajo Nation	Mineral Owner Federal	Lease No. <input type="checkbox"/>
--------------------------------	--------------------------	------------------------------------

LOCATION OF RELEASE

Unit Letter P	Section 10	Township 30N	Range 16W	Feet from the 700'	North/South Line South	Feet from the 500'	East/West Line East	County <input type="checkbox"/> San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---

NATURE OF RELEASE

Type of Release Oil & Water	Volume of Release 20 BBLs (10 bbls oil 10bbls water)	Volume Recovered <input type="checkbox"/> 0
Source of Release Flowline rupture	Date and Hour of Occurrence 04/08/02 7:00 am	Date and Hour of Discovery <input type="checkbox"/> 04/08/02 7:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? 04/08/02 4:00pm	Denny Foust
By Whom? <input type="checkbox"/> Gene Martin	Date and Hour <input type="checkbox"/> 04/08/02 4:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Main flowline leak approximately 20 feet north west of well location. Leak covered 10' x 20' area. Shut-in wells tied to that flowline and shut down flowline. Built berm to contain spill after discovery. Flowline currently out of service. Flowline will have to be dug up to repair and will remain out of service until repaired.

Describe Area Affected and Cleanup Action Taken.*

Area affected approximately 10' X 20'. Propose remediating affected area in place by tilling the soil once a week until it reaches NMOCD standards for btex and pph. Will begin testing in July.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Printed Name: Kenneth W. Jackson	OIL CONSERVATION DIVISION Denny Foust Approved by <input type="checkbox"/> District Supervisor For Frank Chavez
Title: Regulatory Compliance	Approval Date: 04/23/02 Expiration Date:
Date: 04/09/02 Phone: (281) 931-3800	Conditions of Approval: Dig up contamination and treat on site. Cannot till in place. Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

ADGF0209936801