

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 24525

OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Coleman Oil and Gas	Contact	Paul Thompson
Address c/o	Walsh Engr. 7415 E. Main St., Farmington, NM	Telephone No.	327-4892
Facility Name	Chaco Plant #17R	Facility Type	Gas Well

Surface Owner	Navajo Allotted	Mineral Owner	Navajo Allotted	Lease No.	NOO-C-14-20-4324
---------------	-----------------	---------------	-----------------	-----------	------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	14	26N	12W	1830	North	1070	East	San Juan

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	5 bbls	Volume Recovered	0
Source of Release	Stuffing Box	Date and Hour of Occurrence		Date and Hour of Discovery	7 AM 3/14
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There have been several incidences where someone has shut in the line from the well to the tank, which causes the tubing pressure to increase to the point where the stuffing box leaks. Other valves on location have been closed by unknown persons. The well is checked daily by Walsh personnel but the problems occur at night. The stuffing box has been re-built.

Describe Area Affected and Cleanup Action Taken.*

The only area affected is around the well head and pump jack. The water was allowed to dry and the salt stain was covered up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Paul C. Thompson</i>	OIL CONSERVATION DIVISION	
Printed Name: Paul C. Thompson	Approved by District Supervisor: <i>Donny Fount</i>	<i>for Frank Chavez</i>
Title Agent	Approval Date: <i>0/3/21/02</i>	Expiration Date:
Date: 3/15/02	Phone: 327-4892	Conditions of Approval: <i>Break up salt staining donot cover it up.</i>
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGF0208025501