


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30-045-28334

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company West Largo Corp.	Contact J.P. Garrett
Address 8801 S. Yale, Ste. 240 Tulsa, OK 74137	Telephone No. (918) 492-3239
Facility Name Kendall #2402	Facility Type Producing Gas Well

Surface Owner Various	Mineral Owner Various	Lease No. Fee
--------------------------	--------------------------	------------------

LOCATION OF RELEASE

Unit Letter K	Section 24	Township 29N	Range 10W	Feet from the 1550	North/South Line South	Feet from the 1900	East/West Line West	County San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	--------------------

NATURE OF RELEASE

Type of Release Produced (Salt) Water & Crude Oil	Volume of Release 55 BBLs	Volume Recovered ALL Lost All fluid
Source of Release Stock Tank	Date and Hour of Occurrence 1-7-02 :1:00 a.m. (est)	Date and Hour of Discovery 1-7-02: 9:00 a.m.
Was Immediate Notice Given? Was Required <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* 2" Transfer valve at base of stock tank froze in cold weather and split, spilling water and oil on ground(contained within dyke). Valve replaced and re-insulated.		
Describe Area Affected and Cleanup Action Taken.* Ground within tank battery/dyke covered with spilled fluid. Envirotech called onsite, vacuumed all fluid and top 3" of soil, removed to disposal. Removed soil and replaced with new topsoil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: [Signature]	OIL CONSERVATION DIVISION	
Printed Name: J.P. Garrett	Approved by: [Signature] Deputy Superintendent District Supervisor: [Signature] Frank Chavez	
Title: President	Approval Date: 01/16/02	Expiration Date:
Date: 1-10-02 Phone: (918) 492-3239	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGFO201652399