

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Monica D. Johnson
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-326-9829
Facility Name	Allison #47M	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NM-04207

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	8	T32N	R6W	1110'	South	1570'	East	San Juan

Latitude 36.99078° Longitude 107.47752°




NATURE OF RELEASE

Type of Release - Produced water	Volume of Release - 10 BBL	Volume Recovered - none
Source of Release: Produced water pit tank overflowed	Date and Hour of Occurrence 1/13/08	Date and Hour of Discovery 1/18/08 - 8:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - OCD - via email Herman Lujan - BLM - via email	
By Whom? Monica D. Johnson	Date and Hour - 1/28/08 - 2:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*	RCVD JAN 29 '08 OIL CONS. DIV.	

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips Company MSO (lease operator) discovered a produced water spill of approximately 10 BBL at the Allison Unit #47M on the morning of 1/18/08, due to a produced water pit tank overflowing. This occurred due to the fluids in the pit tank being frozen, and when the muffler blew water into the pit tank, it reflected off the ice in the tank onto the ground surrounding the pit tank. All spilled fluids remained within the bermed area, but none was recovered.**

Describe Area Affected and Cleanup Action Taken.* **All spilled fluids remained within the bermed area, but none was recovered. The muffler will be disconnected and dump lines installed inside the pit tank. Once the frozen spilled fluids melt, fertilizer will be raked in to the impacted soil to promote rehabilitation, and will be evaluated for any further remediation (excavation) if needed.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Monica D. Johnson	Approved by District Supervisor:  For: 		
Title: Senior Environmental Scientist	Approval Date: 1-29-08	Expiration Date:	
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 1/28/08	Phone: 505-326-9829		

* Attach Additional Sheets If Necessary

n 6P0804350381