

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 2002

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 30318

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Richardson Operating Company	Contact	<input type="checkbox"/> Lori McCabe
Address	3100 La Plata Highway, Farmington, NM 87401	Telephone No.	<input type="checkbox"/> 564-9084
Facility Name	Ms. Nona #2	Facility Type	<input type="checkbox"/> Gas Producer

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	<input type="checkbox"/> NM-28820
---------------	-----	---------------	-----	-----------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section 15	Township 30N	Range 14W	Feet from the 920'	North/South Line FNL	Feet from the 970'	East/West Line FEL	County San Juan County, NM
-------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-------------------------------

NATURE OF RELEASE

Type of Release	Broken Water Line	Volume of Release	Less than 5 bbl	Volume Recovered	<input type="checkbox"/>
Source of Release	Water Injection Line	Date and Hour of Occurrence	06/28/02 12:00 P.M.	Date and Hour of Discovery	Same
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Originally reported by the public. Denny Faust called Anne Jones			
By Whom?	<input type="checkbox"/> Anne Jones	Date and Hour <input type="checkbox"/> 06/28/02 2:00 P.M.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Air in line caused line to rupture; shut off downstream

Describe Area Affected and Cleanup Action Taken.*
Evaporation, Repaired line by hot patching (welding) replacement section: 15' to 20' long.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lori McCabe</i>	OIL CONSERVATION DIVISION	
Printed Name: Lori McCabe	Approved by <input type="checkbox"/> District Supervisor: <i>Denny Faust</i>	For Frank Chavez
Title: Land Dept.	Approval Date: 07/08/02	Expiration Date:
Date: 07/01/02	Phone: 564-3100	Conditions of Approval: Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGF 0218956065