

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy Inc.	Contact Kim Champlin	
Address #382 County Road 3100 Aztec, NM 87410	Telephone No. (505) 333-3100	
Facility Name Ashcroft SWD #1 (API 30-045-30788)	Facility Type Salt Water Disposal	
Surface Owner State	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	26	29N	11W	795	North	2114	East	San Juan

Latitude 36.70138 Longitude 107.95863

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Approx 15 bbl	Volume Recovered Approx 15 bbl
Source of Release Drain valve/Sump tank	Date and Hour of Occurrence 01/23/08, time unknown	Date and Hour of Discovery 01/23/08 at 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour RCUD JAN 31 '08	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	OIL CONS. DIV. DIST. 3	
Describe Cause of Problem and Remedial Action Taken * <input type="checkbox"/> An XTO employee discovered a release on location. After investigation it was discovered that the drain valve on the #2 filter pot was left open which caused the pump house sump to overflow. Approximately 15 barrels of produced water was released. The release was contained and no produced water left location. The ground was frozen allowing for no or very little absorption into the ground. A vac truck was dispatched and recovered approximately 15 barrels.		
Describe Area Affected and Cleanup Action Taken.* <input type="checkbox"/> The water was contained within secondary containment, no water left location. The valve was closed and a vac truck was dispatched immediately. Vac truck recovered approximately 15 barrels of produced water.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations		

Signature: <i>Kim Champlin</i>	OIL CONSERVATION DIVISION	
Printed Name: Kim Champlin	Approved by District Supervisor <i>Frank Bell</i> For: <i>Charles Perrin</i>	
Title: Environmental Representative	Approval Date 1-31-08	Expiration Date
E-mail Address: Kim_Champlin@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/30/08 Phone: 505-333-3100		

* Attach Additional Sheets If Necessary

nB0804349501