

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-31749		OPERATOR	<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company BP America	Contact Kevin Hansford	RECD JUNE 13 2007		
Address 200 Energy Court	Telephone No. (505) 326-9279	OIL CON. DIV.		
Facility Name Gelbke Com 1M	Facility Type Gas Well	DIST 2		
Surface Owner Federal	Mineral Owner	Lease No NMSF079691		

LOCATION OF RELEASE



Unit Letter E	Section 11	Township 31N	Range 11W	Feet from the 1970	North Line	Feet from the 1040	West Line	County San Juan
------------------	---------------	-----------------	--------------	-----------------------	------------	-----------------------	-----------	--------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Gas	Volume of Release 238 MCF	Volume Recovered 0
Source of Release: Plunger Lubricator	Date and Hour of Occurrence: 1/3/07 12:00pm	Date and Hour of Discovery 14/5/06 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The plunger wore a hole in the lubricator releasing 238 mcf.		
Describe Area Affected and Cleanup Action Taken.* The well was shut in and the lubricator was replaced. The lubricator has been returned to the supplier to undergo a failure analysis.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Kevin Hansford	Approved by District Supervisor:  For: Charlie Perrin		
Title: Field Environmental Coordinator	Approval Date: 1-13-07	Expiration Date:	
E-mail Address: hanske@bp.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 1/16/07	Phone: 505-326-9279		

* Attach Additional Sheets If Necessary

nBP071103 2592