

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9829
Facility Name	San Juan 32 Federal 13 #1A	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NM SF-079329

API # 30-045-31849

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	13	T32N	R9W	1350'	South	1450'	East	San Juan

Latitude 36.98055° N Longitude 107.72715° W

NATURE OF RELEASE

Type of Release – Produced water	Volume of Release – 5 BBL	Volume Recovered – none
Source of Release: Pumping unit stuffing box leak	Date and Hour of Occurrence 11/12/07	Date and Hour of Discovery 11/12/07 – 10:40 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – OCD – via email Mark Kelly – BLM – via email	RCVD NOV 14 '07 OIL CONS. DIV.
By Whom? Monica D. Johnson	Date and Hour – 11/13/07 – 11:00 a.m.	DIST 3
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips Company MSO (lease operator) discovered a Fruitland Coal produced water spill of 5 BBL at the San Juan 32 Federal 13 #1A on the morning of 11/12/07, due to a stuffing box leak on the pumping unit. All spilled fluids remained on location, but none was recoverable. Upon discovery, the pumping unit was shut down and the packing replaced.**

Describe Area Affected and Cleanup Action Taken.* **All spilled fluids remained on location, but none was recoverable. The affected soil was allowed to dry and was raked to promote rehabilitation. The pumping unit will be realigned to prevent improper wear on the stuffing box packing to prevent this from reoccurring in the future.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Johnson</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Monica D. Johnson	Approved by District Supervisor: <i>Brandon Powell</i>	For: <i>Charlie Perrin</i>
Title: Senior Environmental Scientist	Approval Date: <i>11/14/07</i>	Expiration Date:
E-mail Address: <u>monica.johnson@conocophillips.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/13/07	Phone: 505-326-9829	

* Attach Additional Sheets If Necessary

nBPO73U044496