

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Juanita Farrell
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3419
Facility Name	Navajo Allotted Com 1E	Facility Type	Producing Gas Well
Surface Owner	Navajo Indian Tribe	Mineral Owner	Navajo Indian Tribe
		Lease No.	14-20-603-1343
			API # 30-045-26276

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	24	T25N	R10W	1620'	South	860'	East	San Juan

Latitude 36.383803° Longitude 107.842120°

NATURE OF RELEASE

Type of Release - Condensate / Produced Water	Volume of Release - 50 BBL Condensate / 10 BBL Water	Volume Recovered - none
Source of Release: 3 holes in tank - above the bottom weld seam	Date and Hour of Occurrence 3/21/05	Date and Hour of Discovery 3/21/05 - 11:30 am.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Monica Kueling - OCD - via phone Denny Foust - OCD - email Larry Pixley - BIA-Phone/Email	
By Whom? Juanita Farrell	Date and Hour - 3/21/05 - 2:30 p.m. via e-mail/phone	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken.* A condensate / produced water spill of an estimated 50 BBL condensate and 10 BBL produced water was discovered on Monday, 3/21/05 by the lease operator. The spill resulted from 3 holes (above bottom weld seam) in condensate tank. The spilled fluids apparently soaked into the soil, as there was no standing fluid to be recovered. Well was shut in at 11:30 a.m., 03/21/05.

Describe Area Affected and Cleanup Action Taken.* The spilled fluids were contained in the bermed area and soaked into the soil surrounding the condensate tank. Tank will be repaired or replaced. A one-call notification will be made and then remediation activities will begin, tentatively scheduled for end of this week. The spill area will be excavated and all stained soil will be taken to the Envirotech landfarm. Unless further information is discovered upon remediation activities, this will be the final report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Juanita Farrell</i>	OIL CONSERVATION DIVISION	
Printed Name: Juanita Farrell	Approved by District Supervisor: <i>Denny Foust for Charlie Perrin</i>	
Title: Regulatory Analyst	Approval Date: 4/07/05	Expiration Date:
E-mail Address: Juanita.r.farrell@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/01/2005	Phone: 505-599-3419	

* Attach Additional Sheets If Necessary

NDG-F050905 4890