

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Juanita Farrell
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3419
Facility Name	San Juan 28-7 #195M	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-078417

API # 30-039-21689

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	16	T28N	R7W	1550'	South	1840'	East	Rio Arriba

Latitude 36.658185° Longitude 107.576191°

#### NATURE OF RELEASE

Type of Release – Fire	Volume of Release – 0	Volume Recovered – 0
Source of Release:	Date and Hour of Occurrence 12/28/05	Date and Hour of Discovery 12/28/05 – 2:45 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust – OCD – via phone and email Mark Kelly – BLM – via email	
By Whom? Juanita Farrell	Date and Hour – 12/29/05 – 7:45am.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully *		

Describe Cause of Problem and Remedial Action Taken \* This is an initial and final report for a fire that occurred at the 28-7 #195M location on or before 12/28/05. The fire was not observed by any of our personnel, so the exact time of the blaze cannot be determined. Physical evidence of fire damage to equipment at the site was discovered on the 28th during a routine visit by ConocoPhillips Multi-Skilled Operator. The fire damaged both the dehy/separator combo unit and the water pit tank.

Describe Area Affected and Cleanup Action Taken.\* The damage appears to be minor: the dehy/separator unit has bubbled paint on the side of the reboiler, but no other visible damage; the metal lid on the water pit tank is sagging but intact. The well has been shut-in pending results of an investigation into this incident and a complete inspection of the equipment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Juanita Farrell</i>	OIL CONSERVATION DIVISION	
Printed Name: Juanita Farrell	Approved by District Supervisor: <i>Denny Foust</i> for Charlie Perry	
Title: Regulatory Analyst	Approval Date: 1/20/06	Expiration Date:
E-mail Address: juanita.r.farrell@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/29/05 Phone: 505-599-3419		

\* Attach Additional Sheets If Necessary

n DGF 0602040753