

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-24808

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Williams Production	Contact Michael K. Lane
Address PO Box 640	Telephone No. 505-634-4219
Facility Name Rosa 272	Facility Type Well Site

Surface Owner USFS	Mineral Owner BLM	Lease No.
---------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter L	Section 35	Township 31 N	Range 05W	Feet from the 2510	North/South Line FSL	Feet from the 790	East/West Line FWL	County Rio Arriba
-------------------------	----------------------	-------------------------	---------------------	------------------------------	--------------------------------	-----------------------------	------------------------------	-----------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 60 bbl	Volume Recovered 60 bbl
Source of Release Produced Water Tank	Date and Hour of Occurrence Prior 8/14/06 ~18:00 PM	Date and Hour of Discovery 8/14/06 ~18:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Steve Hayden: NMOCD & JJ Miller: USFS	
By Whom? Myke Lane, WPX	Date and Hour 8/15/06 9:30 AM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.



Describe Cause of Problem and Remedial Action Taken.

Trucking company failed to haul tank before it overfilled. All liquid within secondary containment. Possible problem with telemetry and dispatch, checking telemetry and route schedules.

Describe Area Affected and Cleanup Action Taken.

All water recovered from secondary containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane	Approved by District Supervisor:  For: Charlie Perrin	
Title: SJB EH&S Specialist	Approval Date: 8/15/06	Expiration Date:
E-mail Address: myke.lane@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/15/06 Phone: (505) 330-3198		

* Attach Additional Sheets If Necessary

~BP0623429537