

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

APC # 30-039-24808

Name of Company <b>Williams Production</b>		Contact <b>Michael K. Lane</b> <input type="checkbox"/>	
Address <b>PO Box 640</b>		Telephone No. <b>505-634-4219</b> <input type="checkbox"/>	
Facility Name <b>Rosa 272</b>		Facility Type <b>Well Site</b> <input type="checkbox"/>	
Surface Owner <b>BLM</b>		Mineral Owner <b>BLM</b>	Lease No. <input type="checkbox"/>


LOCATION OF RELEASE

Unit Letter <b>L</b>	Section <b>35</b>	Township <b>31 N</b>	Range <b>05W</b>	Feet from the <b>2510</b>	North/South Line <b>FSL</b>	Feet from the <b>790</b>	East/West Line <b>FWL</b>	County <b>Rio Arriba</b> <input type="checkbox"/>
-------------------------	----------------------	-------------------------	---------------------	------------------------------	--------------------------------	-----------------------------	------------------------------	--

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release <b>Produced Water</b>	Volume of Release <b>~20 bbl</b>	Volume Recovered <b>~15 bbl</b>
Source of Release <b>BGT</b>	Date and Hour of Occurrence <b>&lt;3/20/06 9:20 AM</b>	Date and Hour of Discovery <b>Same</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>20</b>	
By Whom? <b>Michael Lane</b>	Date and Hour <b>3/06/06 13:30 MST</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully		
Describe Cause of Problem and Remedial Action Taken. <b>Production Tanks ran over due to water hauler failing to pickup in a timely manner. Automatic tank gauge malfunctioning and to be adjusted. Produced water recovered from secondary containment.</b>		
Describe Area Affected and Cleanup Action Taken.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		



Signature:		OIL CONSERVATION DIVISION	
Printed Name: <b>Michael K. Lane</b>		Approved by District Supervisor:	
Title: <b>SJB EH&amp;S Specialist</b>		Approval Date: <b>3/24/06</b>	Expiration Date:
E-mail Address: <b>myke.lane@williams.com</b>		Conditions of Approval:	
Date: <b>3/20/06</b> Phone: <b>(505) 330-3198</b>		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

N 06F 0608353025