

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-24982

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Williams Production Co, LLC	Contact	Michael K. (Myke) Lane
Address	PO Box 640 / Aztec, NM 87410	Telephone No.	(505) 634-4200
Facility Name	Rosa Unit 262	Facility Type	Well Site

Surface Owner	USFS	Mineral Owner	BLM	Lease No.	
---------------	------	---------------	-----	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	21	31N	05W	2510	FNL	890	FEL	Rio Arriba

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	~50 BBL	Volume Recovered	~50BBL
Source of Release	Storage Tank	Date and Hour of Occurrence	1/7/08 Prior to 13:30	Date and Hour of Discovery	1/7/08 13:30
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell, NMOCD Aztec District		
By Whom?	Myke Lane	Date and Hour	01/07/08 15:25		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	RCVD JAN 9 '08		

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

Water hauler left drain valve to produced water tank. Driver failed to follow procedure after draining tank. Should have blocked drain valve with bull plug to minimize possible leaks if valve not fully closed.

Describe Area Affected and Cleanup Action Taken.*

Well shut-in until tank secured and water recovered from secondary containment. Meeting with contractor to discuss need for additional spill prevention measures.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane		Approved by District Supervisor:  For: Charlie Perrin	
Title: EH&S Team Leader		Approval Date: 1-9-08	Expiration Date:
E-mail Address: myke.lane@williams.com		Conditions of Approval:	
Date: 1/7/08	Phone: 505-634-4219	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

NBP080942221