

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECD NOV 13 06  
OIL CONSERV. DIV.  
DIST. 3  
State of New Mexico  
Energy, Minerals and Natural Resources

Form C-141  
Revised June 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

30-039-25017

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	COP San Juan 31-6 Unit 216	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NMSF078999

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	31N	6W	1162	North	1200	East	Rio Arriba

#### NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	20 BBLS.	Volume Recovered	18 BBLS.
Source of Release	Water Storage Tank	Date and Hour of Occurrence	11/9/2006 2:30:00 PM	Date and Hour of Discovery	11/9/2006 2:30:00 PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell (message)		
By Whom?	Ed Hasely	Date and Hour	11/10/2006 7:10:00 A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken \*

The water pump failed to start due to a bad Murphy tank switch and the tank overflowed approximately 20 bbls of water.

Describe Area Affected and Cleanup Action Taken.\*

All fluids were contained on location. A vacuum truck was used to recover all free standing fluids (18 bbls recovered). The impacted soils will be raked as necessary to break up any crust that may form.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name:	Approved by District Supervisor	For: Charlie Perrin	
Title	Environmental Representative	Approval Date:	11/13/06
E-mail Address:	lhasely@br-inc.com or gwurtz@br-inc.com	Expiration Date:	
Date:	11/10/06	Conditions of Approval	Attached <input type="checkbox"/>
Phone:	(505) 326-9841 or 9537		

\* Attach Additional Sheets If Necessary

nBP0632553086