

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039-29614

OPERATOR

x Initial Report Final Report

Name of Company: Devon Energy Production Co. L.P.	Contact: Steve Zink
Address: P.O. Box 6459 Navajo Dam N.M 87419	Telephone No. 505-320-0677
Facility Name: NEBU 466A	Facility Type: Coal seam well site

Surface Owner: BOR	Mineral Owner: Federal	Lease No. SF- 079003
--------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter O	Section 34	Township 31-N	Range 7-W	Feet from the 70	North/South Line South	Feet from the 1790	East/West Line East	County Rio Arriba
------------------	---------------	------------------	--------------	---------------------	---------------------------	-----------------------	------------------------	----------------------

NATURE OF RELEASE

Type of Release: Salt Water	Volume of Release: 20 bbl	Volume Recovered: 18 bbl
Source of Release: water tank	Date and Hour of Occurrence 12-1-06 5:00P.M	Date and Hour of Discovery 12-2-06 12:30 P.M
Was Immediate Notice Given? Not Required X Yes (within 24 hrs) <input type="checkbox"/> No <input type="checkbox"/>	If YES, To Whom? Brandon Powell	RCVD DEC 11 06 OIL CONSV. DIV. DIST. 3
By Whom? Steve Zink	Date and Hour 12-3-06 10:23 A M	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse	



If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken.* Roustabouts left a valve off the tank when building site; we turned on a pump jack started pumping water Installed a valve on the tank.

Describe Area Affected and Cleanup Action Taken.*

A 100'x60' inside the tank berm was covered with water. Called water truck and had them suck up all standing water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Zink	Approved by <input type="checkbox"/> District Supervisor  For: Charlie Perrin	
Title: Sr. Production Foreman	Approval Date 12-11-06	Expiration Date.
Date: 12/8/06 Phone: 505-320-0677	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

nBP0634551735