

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-30191

OPERATOR

Initial Report Final Report

Name of Company XTO Energy Inc.	Contact Kim Champlin
Address #382 County Road 3100 Aztec, NM 87410	Telephone No. (505) 333-3100
Facility Name Jicarilla Apache #10G	Facility Type Gas Well

Surface Owner Jicarilla Apache	Mineral Owner	Lease No. JIC 154
---------------------------------------	---------------	--------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	27	26N	05W	2175	North	2355	West	Rio Arriba

Latitude 36 45892N Longitude 107.34737W

NATURE OF RELEASE

Type of Release KCI Water	Volume of Release Approx 82 bbl	Volume Recovered Approx 72 bbl
Source of Release Flow Back Tank	Date and Hour of Occurrence 09/29/07, 4:40 AM	Date and Hour of Discovery 09/29/07 4:40 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cordell TeCuba and Dixon Sandoval- Jicarilla Apache Nation Brandon Powell- NMOCD	
By Whom? Lisa Winn	Date and Hour 09/29/07 12 00 PM & 09/30/07 8 00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse NA	

RCVD OCT 18 '07
OIL CONSV. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully *
NA

Describe Cause of Problem and Remedial Action Taken * On September 28, 2007 the well was set and put online for flow back. The well had 900 psi on casing and was opened on a 1/4" choke. The well was flowing CO2 and water. During operations the vent line froze and exploded off the tank releasing approximately 82 barrels of frac fluid onto the ground along with a grouping of sagebrush approximately 100' X 100' being sprayed with a very light mist. It was all contained on location. Appropriate notifications were made and a vac truck dispatched. Approximately 72 barrels was recovered.

Describe Area Affected and Cleanup Action Taken * A vac truck was used to recover the material on location. There was minimal staining on the ground and no staining on the sagebrush. The contaminated soil was excavated and disposed of at a licensed facility and then raked. The flow back tank was changed out.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: <i>Kim Champlin</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name Kim Champlin	Approved by District Supervisor. <i>Bob Bell</i> For: <i>Charlie Perrin</i>	
Title: Environmental Assistant	Approval Date 10-18-07	Expiration Date:
E-mail Address: Kim_Champlin@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date 10/13/07 Phone: 505-333-3207		

* Attach Additional Sheets If Necessary

nBP0732529760