

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-045-09261

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company XTO Energy Inc.	Contact Lisa Winn	ROUND DEC 27, 06
Address 2700 Farmington Ave, Bldg K, Ste. 1, Farmington, NM 87401	Telephone No. (505) 566-7942	OIL CON. DIV.
Facility Name Federal C #1	Facility Type Gas Well (Dakota)	DIST. 3
Surface Owner Fed	Mineral Owner Fed	Lease No. NMSF 078977

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	30	30N	13W	790	North	790	East	San Juan

Latitude 36.78934 Longitude 108.23957

NATURE OF RELEASE

Type of Release Water, mud, cement	Volume of Release Approx 8 bbl	Volume Recovered Approx 8 bbl
Source of Release Communication between well and offset well during well treatment activities.	Date and Hour of Occurrence 12/06/06, approx. 11:30 am	Date and Hour of Discovery 12/06/06 at approx. 11:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin	
By Whom? Lisa Winn, XTO Energy	Date and Hour 12/06/06 at approx. 3:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully * N/A		
Describe Cause of Problem and Remedial Action Taken * <input type="checkbox"/> While treating an offset well, mud, cement, water and sand began flowing around wellhead. The water was contained by constructing earthen berms around the well head.		
Describe Area Affected and Cleanup Action Taken * <input type="checkbox"/> Impacted soil was limited to the area around the well head. The soil was stabilized on site using spoils pile and hauled to a local landfarm.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Winn	Approved by District Supervisor.  For: Charlie Perrin	
Title Environmental Coordinator	Approval Date 12-27-06	Expiration Date:
E-mail Address Lisa_Winn@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/21/06 Phone: 505-566-7942		

* Attach Additional Sheets If Necessary

nBP 0701743021