

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-09680

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company XTO Energy Inc.	Contact Lisa Winn
Address 2700 Farmington Ave, Bldg K, Ste. 1, Farmington, NM 87401	Telephone No. (505) 566-7942
Facility Name Chrisman GC #1	Facility Type Gas Well



Surface Owner BLM	Mineral Owner BLM	Lease No.
--------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	11	30N	12W	2165	South	1090	West	San Juan

Latitude 36.82547 Longitude 108.07228

NATURE OF RELEASE

Type of Release Water with Potassium Chloride (2% soln)	Volume of Release Approx 20 bbl	Volume Recovered N/A
Source of Release Leak in a rig pit (open tank)	Date and Hour of Occurrence 02/10/06, time unknown	Date and Hour of Discovery 02/10/06 at 7:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully * NA		
Describe Cause of Problem and Remedial Action Taken * <input type="checkbox"/> An XTO employee discovered water leaking from a rig pit upon arriving at the location. Approximately 20 bbl of water leaked from the tank with less than 5 bbl running on the road leading into the location. The remaining water was removed from the tank and the tank was replaced.		
Describe Area Affected and Cleanup Action Taken * The impacted area was limited to the well pad and approximately 50 linear feet of road leading into the location. The affected dirt along the road was dragged and brought back on location; the soil was spread over the well pad.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Winn	Approved by District Supervisor: 	
Title: Environmental Specialist	Approval Date 2/21/06	Expiration Date:
E-mail Address: Lisa_Winn@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/14/06	Phone: 505-566-7942	

* Attach Additional Sheets If Necessary

N DG-F0605551113