

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-04523779

OPERATOR

Initial Report

Final Report

Name of Company XTO Energy Inc.	Contact Lisa Winn	
Address 2700 Farmington Ave, Bldg K, Ste. 1, Farmington, NM 87401	Telephone No. (505) 566-7942	
Facility Name Stanolind Gas Com #1 SWD	Facility Type Salt Water Disposal	
Surface Owner BLM	Mineral Owner BLM	Lease No. NMNM019414

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	17	32N	12W	1820	South	1590	East	San Juan

Latitude 36.98387 Longitude 108.11442

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release >35 bbl	Volume Recovered Approx 35 bbl
Source of Release tank overfilled	Date and Hour of Occurrence 02/18/06, time unknown	Date and Hour of Discovery 02/18/06 at 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust and Sherry Landon (BLM)	
By Whom? Lisa Winn	Date and Hour Reported to Denny Foust at 12:30 pm on 02/18/06	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* ☐ A high-high automation alarm failed and a SWD tank ran over spilling more than 35 bbls of water. The water was contained within the secondary containment structure and recovered by vacuum truck.

Describe Area Affected and Cleanup Action Taken.* ☐ The water was contained within the secondary containment structure around the tank. The spill was detected promptly and a vacuum truck was dispatched immediately to the site. Quick response resulted in an efficient recovery of water and no observed impact to the location. The alarm was repaired immediately and tested.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lisa Winn</i>	OIL CONSERVATION DIVISION	
Printed Name: Lisa Winn	Approved by District Supervisor: <i>Denny Foust for Charlie Perrin</i>	
Title: Environmental Specialist	Approval Date:	Expiration Date:
E-mail Address: Lisa_Winn@xtoenergy.com	Conditions of Approval.	Attached <input type="checkbox"/>
Date: 02/24/06 Phone: 505-566-7942		

* Attach Additional Sheets If Necessary

NDGF0607242507

