<u>District I</u>
1625 N French Dr , Hobbs, NM 88240
<u>District II</u>
1301 W Grand Avenue, Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410
<u>District IV</u>
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action 30-045-23719

30.045-23719						OPERATOR			Initial Report X Final Report			
Name of Company XTO Energy Inc.						Contact Lisa Winn				•		
Address 2700 Farmington Ave, Bldg K, Ste. 1						Telephone No. (505) 566-7942						
Farmington, NM 87401												
Facility Name Stanolind Gas Com #1 SWD						Facility Type Salt Water Disposal						
Surface Owner Federal Mineral Owner						BLM			Lease No. NMNM019414			
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the		/South Line Feet from the East/West Line County						
J	17	32N	12W	1820	South		1590	East		San Juan		
Latitude 36.98387 Longitude 108.11442												
NATURE OF RELEASE												
Type of Rele	ase Produ	ced Water		11/2	Volume of Release Approx 200 Volume Recovered Approx 200 bbl					oprox 200 bbl		
,						bbl			- PF			
Source of Release Tank Overflowed									Date and Hour of Discovery 07/21/06 at 12:00 pm			
Was Immediate Notice Given?						If YES, To Whom?						
X Yes \(\subseteq \text{No} \subseteq \text{Not Required} \)						Brandon Powell						
By Whom ⁹ Lisa Winn						Date and Hour 07/21/06 – approximately 6:00 pm						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes X No						`N/A						
If a Watercourse was Impacted, Describe Fully.* N/A												
Describe Cause of Problem and Remedial Action Taken.* The solar regulator on the call out system failed, draining the batteries. The ESD control												
valve was unable to operate due to this failure allowing the tanks to overflow. A low voltage alarm will be installed to page out notifying												
personnel of potential failure.												
Describe Area Affected and Cleanup Action Taken * The water was contained within the secondary containment structure around the tank. The												
spill was detected promptly and a vacuum truck was dispatched immediately to the site. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
						OIL CONSERVATION DIVISION						
Signature [.]	Hi	z U /z										
// /0°						Approved by	District Supervis	or: 134	I K	211 Fo	r: Charlie Perrin	
Printed Name Lisa Winn Approved by District Supervisor: Beanch Sell For: Charlie Persin												
Title: Environmental Specialist						Approval Date 7/28/06 Expiration Date:						
E-mail Addre	ess. Lisa V	Winn@xtoene	ergy.com			Conditions of	f Approval			A 44 - 1 - 1		
		<u> </u>	566-7942			27778	29 70 Son	Attached .				
Attack Additional Charte If Nancasan												
		1.5 11 1.00000	·)		n	BP062225°	IDIO/P	7.7	7.1			