

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 26275

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company PATINA SAN JUAN, INC.	Contact JEAN MUSE
Address 5802 US HIGHWAY 64	Telephone No. 505-632-8056
Facility Name LANGENDORF #3 SWD	Facility Type SALT WATER DISPOSAL

Surface Owner BLM	Mineral Owner BLM	Lease No. NMSF 078463
--------------------------	--------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	34	31N	13W	1097	SOUTH	1439	EAST	SAN JUAN

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release CONTAINED LEAK	Volume of Release EST 120bbls	Volume Recovered EST 115bbls
Source of Release BROKEN DISCHARGE PRESSURE NIPPLE	Date and Hour of Occurrence after 6:00pm 8/31/06	Date and Hour of Discovery 9:00am 9/01/06
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kelly Roberts, Brandon Powell NMOCD Phone message w/Mark Kelly	
By Whom? KENNY HENDERSHOT AND JEAN MUSE	Date and Hour 9:30am TO NMOCD 10:00am to BLM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

MECHANICAL FAILURE OF A DISCHARGE PRESSURE NIPPLE CAUSED A LEAK. REPLACED NIPPLE AND PULLED SALTWATER OUT OF THE BERM AREA.

Describe Area Affected and Cleanup Action Taken.*

LEAK WAS FULLY CONTAINED WITHIN THE BERM AREA AND WAS PULLED BY A VACUUM TRUCK.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: JEAN M. MUSE		Approved by District Supervisor:  For: Charlie Perrin	
Title: REGULATORY COMPLIANCE		Approval Date: 9/16/06	Expiration Date:
E-mail Address: jmuse@nobleenergyinc.com		Conditions of Approval:	
Date: September 1, 2006 Phone: 505-632-8056		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nBPO625441004