

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-27686

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Kevin Hansford
Address 200 Energy Court	Telephone No. (505) 326-9279
Facility Name Florance GC E3 003	Facility Type Fruitland Coal Well

Surface Owner Federal	Mineral Owner	Lease No. NMNM09717
-----------------------	---------------	---------------------

LOCATION OF RELEASE

Unit Letter M	Section 13	Township 30N	Range 09W	Feet from the 790	South Line	Feet from the 980	West Line	County San Juan
------------------	---------------	-----------------	--------------	----------------------	------------	----------------------	-----------	--------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 10	Volume Recovered 0
Source of Release: Below Grade Tank	Date and Hour of Occurrence: 8/7/06 Evening	Date and Hour of Discovery 8/8/06 9:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* During a site inspection the Production tech. noticed that the berm was washed out on the below grade tank from run off from another location after a significant rain event. The below grade tank overflowed and filled the inside of the berm. All fluids remained inside secondary containment.

Describe Area Affected and Cleanup Action Taken.*

All fluids remained inside the secondary containment. The standing fluids were pulled and the below grade tank was cleaned out. The site will be evaluated for placing the below grade tank in a different location to prevent this from happening again.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Kevin Hansford		Approved by District Supervisor:  For: Charlie Perrin	
Title: Field Environmental Coordinator		Approval Date: 8/17/06	Expiration Date:
E-mail Address: hanske@bp.com		Conditions of Approval:	
Date: 8/17/06 Phone: 505-326-9279		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nBP0623348800