

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-32258

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P. O. Box 420, Farmington, NM 87499-0420	Telephone No.	(505)325-1821
Facility Name	Big Field #9	Facility Type	

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	NM-15654
---------------	---------	---------------	---------	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	15	30N	14W	1960	South	660	West	San Juan

Latitude 36.81222 Longitude 108.30277

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	approx 15 bbls	Volume Recovered	approx 10
Source of Release	Pit overflowed	Date and Hour of Occurrence	10/14/07 @ approx 8:00 p.m.	Date and Hour of Discovery	10/14/07 @ approx 9:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Aztec Office NMOCD - Brandon Powell & BLM Farmington Office - Erinn Shirley		
By Whom?	Rodger Mullins	Date and Hour	10/15/07 @ approx @ approx 2:45 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RCVD OCT 17 '07
OIL CONS. DIV.
DIST. 3

Describe Cause of Problem and Remedial Action Taken.*

Packing in pump came loose causing the pit to overflow. Packing fixed. Spill contained within bermed area. Spread urea on contaminated area.

Describe Area Affected and Cleanup Action Taken.*

Spill contained within bermed area. Spread urea on contaminated area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Rodger Mullins	Approved by District Supervisor: <i>[Signature]</i>	For: Charlie Perrin
Title: Production Foreman	Approval Date: 10-17-07	Expiration Date:
E-mail Address: rmullins@duganproduction.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 16, 2007 Phone: (505)325-1821		

* Attach Additional Sheets If Necessary

u80732452740